FI Con 2 instruction manual for GROM				
Product number 05-04-0016 Applicable model GROM(JC61-1000001 ~) Characteristic This compact controller already has preset data for sever	Thank you for your purchase of our product. Please so you will comply with the following matters at the time of use. Please check your always kit contents before mounting.If there is a point of notice, please consult the dealer of purchase. If the description, such as photos or Illustration different with this part. al engine parts. Injection controller which can be changed the settings easily			
by switching the rotary switch of the main body.Built-in m turning the rotary switch.	aps of the fuel injection, can be increased or decreased slightly by simply			
 bility for compensation. If trouble occurs in the other components with the use not assume any in any such matters. When it is machining like the products and mounting, de Please refrain from inquiries about the product and the This product is a dedicated products of the type of ve Please apply at the repair part number if attached to Only for GROM (JC61) ,which is Japanese domestic official 				
• Precautions on usepurchased dealer.				
vice) to a digital circuit. It will be the cause of product f Ignition system of goods outside the company (ignition coil cause malfunction or failure of the product due to the incre	t a high-voltage noise that adversely affect the ballast / inverter (voltage conversion de- trailure or malfunction, please do not installed simultaneously absolutely. and plug cord) is associated with the up of the ignition voltage, please do not use it can ease of radiation noise. Ifferences in shortages and voltage waveform of the power generation amount, it will be the			
 ful when the car wash likewise. Please immediately stop the of transparent, the humidity is high, suddenly there are of the panel to inhale moisture. Product of the body is made of resin. Use cover, etc. If term left for under harsh conditions such as in a hot wear Please do not disassemble. In addition, Please note if it is Please do not give a heavy shock. Do not performed a stroconnection of the internal parts by the impact, and there On cleaning. Dissolve a small amount of neutral detergent 	ture, and take a rain or water, water might fail to penetrate into the body.Please be care- te use if the water has entered the body.When the switch part of attached to using a panel a change in temperature, etc. the body it may cloudiness occurs in the transparent part in order to prevent deterioration long time to put the motorcycle on the field. When long- ther, it is considered the deterioration and deformation of the resin and rubber parts. Is decomposed by the customer, we will not be able to accept the inspection and repair. Ong shock is transmitted to this product. Unrepairable and failure due to fall off or dis- is a risk of the main body case damage. In the water if there is tough dirt, please slowly carefully dirt. Please note, the use of unds, possibilities and alteration of the resin part, panel will cloudy.			
NOTE When the handling of ignoring this displa	y, property damage and human shows the assumption of what injury.			
 When performing the work, it should be made to prepare th Do the work must always specified torque using a torque we The product and the frame, might have edges or protrusion 	when the engine and the muffler is cold). (It may cause burns.) ne tools for the job. (Breakage of parts, it may cause injury.)			
A Warning When the handling of ignoring this displa	y people died, shows the contents of the serious injury possibility is assumed.			
 When performing the work, do the work safely stabilize the ing.) Inspection, maintenance, the instruction manual or, inspectivately inspection and maintenance, there is a risk that remains when carrying out the inspection and maintenance, etc., if is a risk that lead to accidents Continued use.) 	found damaged parts, replace the damaged parts to avoid possible to reuse the parts. (There ed in a place that is out of reach of children, it should be discarded.			
■ For claims, only to products that have been recognized t we will repair or replace.However all of the cost of such Correct installation and, if it is not protected, such as Please note. If you use in the race, etc., in any case the Until it is destroying the product, please keep this manu	how to use, it does not have this limitation. a claim can not be accepted. al.			
TAKE AND TEL: +81-721-25-1357 FA	Nishikiorihigashi Tondabayashi Osaka JAPAN X:+81-721-24-5059 e-mail:english@takegawa.co.jp URL http:// www.takegawa.co.jp name and country name provided. (Only English please)			

Produc	t content			Part Names
8				Rotary Switch Red LED FI Con 2 panel
No.	Product content	Quantity	Repair Item Number	
1	FI Con 2 Assy.	1	-	
2	Harness Comp.	1	32200-K26-T00	
3	Restore harness Comp.	1	38772-FC3-T00	
4	Subcode (BL/YEL)	1	32231-KWN-T00	
5	Subcode (YEL)		32232-KYJ-T00	※7.FI Con 2 panel (switch unit opening hole) is.
6	Electro tap	2	00-05-0015 (5 pcs)	1. FI Con 2 Assy. To the factory pasted already.
8	FI Con 2 panel (switch unit opening hole) FI Con 2 panel (switch unit clear)	1 ※	38775-FC3-T00	× Please note. Please order in the repair parts are
	Rubber cap		00-05-0045	always repair part number. If it is not the part
10	Velcro tape		00-00-0150	number order, you may not be able to order.
11	Cap ϕ 6	1	00-00-0130	It should be noted. In the case of parts that can
12	Cap ϕ 7.5	1	00-00-0482	not be separately shipment, please order a set part
13	Cable tie 150mm	5	00-00-0135 (10 pcs)	number.

■ Mounting procedure ※With regard to the mounting method and the specified torque of detail, refer to the genuine service manual.

Introduction


This product has been developed on the assumption that the genuine PGM-FI system is operating without problems.


If the PGM-FI system itself there is trouble and upset, it may not work if it is installed the product correctly, not only can not exhibit the performance. It does not could lead to failure is beginning elsewhere this product. Be sure to check that there is no trouble in the PGM-FI system, should be attached and use. In addition, work by using a maintenance stand like a horizontal a safe place, start then fully stabilized to the vehicle.


NOTE

Exterior parts removal work at our instruction manual, we have noted the only summary that omits the details.

If you are unfamiliar with the work, you should better to request it to a shop. Or please be sure to work in accordance with the work procedure of the manufacturer original service manual. Also at the desorption of covers, be carefull not to damage the holding pin part and groove part.







Disconnect the O2 sensor 1P coupler at the back of the ignition coil at right side of the vehicle. Please insert the ϕ 6 cap(smaller) included in the kit to the main harness side, and the ϕ 7.5 cap (larger) to the 02 sensor side coupler.

A NOTE

Please be sure to disconnect the 1P coupler of the O2 sensor. Otherwise, it will be cause that the FI Con 2 does not work correctly at original setting.

When O2 sensor is removed, there is a case that stock ECU recognizes as "O2 sensor abnormality" and turns the engine check lamp. The manufacturer genuine service manual says that "O2 sensor abnormality" means "usually does not change with the operation". So when using FI CON2, please use as it is. (Please turn off once and restart the engine, and then the check lamp will be off.)However, if it frequently lit, there is also the possibility other than O2 sensor abnormality, please inspect the each part.

■ How to Use and Set the FI CON2

▲ Important

FI CON2 requires initial setting. Cannot be start the engine without an initial setting.

A NOTE

Arrow of the switch indicates a setting shown by numbers or alphabet.


Since it has become a hexadecimal notation, equivalently "A" is 10 and "F" is 15.

■ Initial setting of the throttle position sensor/

At the first time after installing the FI CON2 or when you adjusted the throttle body stopper screw(screw to adjust the fully closed position), it is necessary to set the throttle position sensor again.

Also, if you want to change the MAP by changing the engine specifications, please re-set in accordance with the following procedure.

(1) Turn off the key and then set the rotary switch to "0". Throttle grip should be fully closed.




② Turn on the key. Red and green LED light on at the same time. After the red flashes three times, and then both red and green will light off. Then, green LED will begin to flash.



③ Remains in this state, set the rotary switch to the suitable SW number by engine specifications. Please refer on page 7, "MAP Selection Table by engine specification".



④ Slowly fully open the throttle grip, keep fully open for more than 1 second, and then slowly fully close it.



⑤After fully closed, green LED stops flashing and it will remain off. When the green LED turned off, it can be learned successfully the setting of throttle position sensor and the selection of MAP type, to the internal memory of the FI CON2. Even exchange the battery or turn the key OFF, learning contents won't be deleted.

A NOTE


When the grip is fully closed again, if the green LED is continuously flashing, connection failure of yellow sub-code can be considered, or may be kept it fully opened for too short.


6 Turn the key off and then set the rotary switch to "5".

A NOTE

Function of rotary switch of FI CON2, after the MAP selection and learning will be the adjustment of correction value. After the initial setting, first should be set "5" (standard setting).







■ MAP Selection Table by engine specification

Each parts other than the stock parts in a following setting table are all limited to TAKEGAWA parts.

At the initial setting, set the rotary switch to the suitable SW number by engine specifications.

Please note, only is the setting that made the test at our company. vehicle individual difference and the outside air temperature and altitude, rider of body weight, due to an external factor, it might not necessarily be in the best setting.

S	W	Engine specifications.				
	0	-				
Г	1	Stock piston + Sport camshaft + Stock exhaust system				
	2	Stock piston + Sport camshaft + Slip-on silencer				
	3	Stock piston + Sport camshaft + Full exhaust system				
4	4	e-stage + Stock camshaft + Stock exhaust system				
	5	e-stage + Stock camshaft + Slip-on silencer				
	6	e-stage + Stock camshaft + Full exhaust system				
	7	e-stage + Sport camshaft + Stock exhaust system				
1	8	e-stage + Sport camshaft + Slip-on silencer				
	9	e-stage + Sport camshaft + Full exhaust system				
	A	S-stage + Stock camshaft + Stock exhaust system				
E	В	S-stage + Stock camshaft + Slip-on <u>sile</u> ncer				
	С	S-stage + Stock camshaft + Full exhaust system				
	D	S-stage + Sport camshaft + Stock exhaust system				
	E	S-stage + Sport camshaft + Slip-on silencer				
	F	S-stage + Sport camshaft + Full exhaust system				

% In the above table, "-" means no data is set. So please do not set that number to SW.

■ Troubleshooting

— · · · · · · · · · · · · · · · · · · ·	
Even in key ON, LED is also not lit or flashing.	■ Make sure the kill switch is not set to OFF.
	Please check the battery voltage of the red cord of harness Comp. 3P connector
	at key ON.
	■ Make sure the round earth terminal of the green cords are securely connected to
	the frame ground.
At the key ON, both LED remains lit.	■ It is a state that has not been the initial setting of the throttle position
	and MAP selection.
	Please do the initial setting.
Engine does not start.	■ Please re-confirm the wiring connection of harness Comp. connector.
	■ If the initial start-up, make sure the rotary switch indicate "5".
At the key ON, red LED only remains lit.	■ It is a state that is not correctly read the throttle opening signal. Make sure
	there is no problem with the connection of the yellow code.
	■ The main harness has two yellow code.Always must be connected to the yellow
	code of between green / orange and yellow / red.
After the engine is started, the green LED does not	■ It is a state that is not read successfully the crank pulse. Make sure there is
lit.	no problem with the connection of the sub-code (blue / yellow).
After the engine is started, the green LED lit, but	■ At the engine start, if turning on the cell starter while snapping the throttle,
sometimes not lit.	it might become such symptoms. Please start the engine without snapping the
	throttle.
Feel like setting does not match.	■ Make sure the MAP that matches the engine specifications have been correctly
	selected.
	■ Setting of rotary switch during engine operation, rather than a MAP number,
	make sure that indicates standard setting of "5".
	■ The combination of engine parts other than TAKEGAWA, probably not match the
	setting, it may become a cause of idling malfunction or engine stall.
During operation, the engine check lamp is turned	■ On the specifications of the FI Con 2, it will be used to disconnect the genuine
on.	02 sensor coupler, but that genuine ECU engine check lamp is lit as the O2
	sensor abnormality. Since it is also lit there is no change in the settings and
	In addition, the lighting of the engine check lamp by the engine restart will
	disappear. However, if you frequently lit there is a possibility other than the
	O2 sensor abnormality so, please go to each part inspection.